

FORM MR-AR (Revised 12/93)

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

355 West North Temple 3 Triad center, Suite 350 Salt Lake City, Utah 84180-1203 Telephone: (801) 538-5340 Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I. General Information

- 1. Report Time Period: From (mo./yr.) 1/94 To (mo./yr.) 12/94
- 2. DOGM File Number (Mine No.): M/045/004
- 3. Mine Name: Pine Canyon Reclamation Project
- 4. Mineral(s) Mined (or permitted to mine): Copper and associated metals.
- 5. Type of mine: X Surface Mine or Underground Mine
- 6. Legal Description, (Location of Lands Affected):

Portions of the

Section 17, S 1/2, SW 1/4;

Section 20, N1/2, NW 1/4, W 1/2, NE 1/4, SE 1/4, NE 1/4, E 1/2, SE 1/4;

Section 21, SW 1/4, SW 1/4;

Section 28, N 1/2, SW 1/4, NW 1/4;

Section 29, NE 1/4, NE 1/4;

Township 3 South, Range 3 West, Salt Lake Baseline and Meridian, Tooele County, Utah.

- 7. Name of Operator or Company: Kennecott Utah Copper
- 8. Permanent Street Address: P. O. Box 525 City, State, Zip: Bingham Canyon, UT 84006-0525 Phone: (801) 569-6555
- 9. Company Representative (or designated operator):

Name: Frederick D. Fox

Title: Director, Environmental Affairs Business Address: P. O. Box 525

City, State, Zip: Bingham Canyon, UT 84006-0525

Phone: (801) 569-6555

Please check if any of the above information has changed since previous year.

II. Mining and Reclamation

- 1. Was the mine active during the past year? Yes ___ No X
- 2. If active, how much ore or mineral was mined? The mine was not active in 1994.
- 3. How much additional acreage was disturbed during the past year? 0 acres
- 4. Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved.

No new or additional acreage was affected during this reporting period.

- 5. How much acreage was reclaimed during the past year? 0 acres
- 6. Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.

No new reclamation work occurred during this reporting period. The past year was spent monitoring the reclamation work that was performed over the past few years. Reclaimed areas that were not effected by the flash flood in 1993 show significant amounts of established vegetation. The areas repaired from the 1993 flash flood showed successful establishment of initial revegetation.

- 7. What is the total disturbed acreage at years end? 17.3 acres
- Briefly summarize any mining and/or reclamation plans for the upcoming 8. year.

No new reclamation activities are planned for 1995, however, the revegetation will be monitored for success. KUC will apply for partial release of the areas reclaimed in 1988 that were not damaged in the 1993 flash flood. In addition, KUC plans to review and update final designs for the unreclaimed adit and water diversion structure in Pine Canyon.

NOTE:

Section III., "Additional Information" applies only to large mining operations.

Additional Information III.

An updated surface facilities map should be attached if there have been 1. significant changes since the previous map was submitted.

No significant changes occurred since last year. Therefore, no map will be submitted with this report.

Any monitoring results or other reports that are required under the terms 2. of the approved notice of intention should also be submitted.

The following attachments provide the required water monitoring results as described in the approved notice of intent:

- 1994 Pine Canyon Water Sample Results
- 1994 Pine Canyon Water Level Information

IV. Signature Requirement

I hereby certify that the foregoing is true and correct.

Name (Typed or Print): Frederick D. Fox

Title of Operator: Director, Environmental Affairs

Signature of Operator: Trescences

Date: 1/30/95

PCH2OLVL.XLS

1994 PINE CANYON WATER LEVEL INFORMATION

SAMPLE SITE	DATE	WATER ELEV. (AMSL)
Carr Fork Exhaust Shaft Water Level Monthly Summary	1/3/94	6212.12
	2/4/94	6206.18
	3/1/94	6201.9
	4/8/94	6193.48
	5/5/94	6198.12
	6/2/94	6207.36
	7/7/94	6196.6
	8/1/94	6190.2
	9.1/94	6181.6
	10/10/94	6171.7
	11/15/94	6163.48
	12/12/94	6158.13

PC94H2O.XLS

1994 PINE CANYON WATER SAMPLE RESULTS

ANALYTE	MDL	TOTAL	TOTAL	DISSOLVED	DISSOLVED	UNITS
		3/31/94	10/10/94	3/31/94	10/10/94	
pH		7.92	7.79			standard pH unit
conductivity	1	600	633			micro mho/cm
temperature		5.5	9			degrees C
Biological Oxygen Demand	0.1	<mdl< td=""><td>9.13</td><td>Service and Market Services</td><td></td><td>mg/l</td></mdl<>	9.13	Service and Market Services		mg/l
total coliform	1	<mdl< td=""><td>58</td><td></td><td></td><td>colonles/100ml</td></mdl<>	58			colonles/100ml
fecal coliform	1	<mdl< td=""><td><mdl< td=""><td></td><td></td><td>colonles/100ml</td></mdl<></td></mdl<>	<mdl< td=""><td></td><td></td><td>colonles/100ml</td></mdl<>			colonles/100ml
total dissolved solids	5	393	436		8636	mg/l
total suspended solids	1	<mdl< td=""><td><mdl< td=""><td></td><td></td><td>mg/l</td></mdl<></td></mdl<>	<mdl< td=""><td></td><td></td><td>mg/l</td></mdl<>			mg/l
oil and grease	1	<mdl< td=""><td><mdl< td=""><td></td><td></td><td>mg/l</td></mdl<></td></mdl<>	<mdl< td=""><td></td><td></td><td>mg/l</td></mdl<>			mg/l
phenol	0.001	<mdl< td=""><td><mdl< td=""><td></td><td></td><td>mg/l</td></mdl<></td></mdl<>	<mdl< td=""><td></td><td></td><td>mg/l</td></mdl<>			mg/l
calcium	0.1	79	70			mg/l
chloride	5	34	10	and the second		mg/l
EPA total cyanide	0.005	<mdl< td=""><td><mdl< td=""><td></td><td></td><td>mg/l</td></mdl<></td></mdl<>	<mdl< td=""><td></td><td></td><td>mg/l</td></mdl<>			mg/l
potassium	0.1	1.3	1.7	44.0		mg/l
magnesium	0.1	38	40.6			mg/l
sodium	0.1	17	13			mg/l
sulfate	5	139	142			mg/l
arsenic	0.004	0.006	0.13	0.006	0.011	mg/l
cadmium	0.001	<mdl< td=""><td><mdl< td=""><td><mdl< td=""><td><mdl< td=""><td>mg/l</td></mdl<></td></mdl<></td></mdl<></td></mdl<>	<mdl< td=""><td><mdl< td=""><td><mdl< td=""><td>mg/l</td></mdl<></td></mdl<></td></mdl<>	<mdl< td=""><td><mdl< td=""><td>mg/l</td></mdl<></td></mdl<>	<mdl< td=""><td>mg/l</td></mdl<>	mg/l
copper	0.01	0.05	<mdl< td=""><td>0.04</td><td><mdl< td=""><td>mg/l</td></mdl<></td></mdl<>	0.04	<mdl< td=""><td>mg/l</td></mdl<>	mg/l
iron	0.03	0.03	0.06	0.03	<mdl< td=""><td>mg/l</td></mdl<>	mg/l
nickel	0.005	0.009	<mdl< td=""><td>0.007</td><td><mdl< td=""><td>mg/l</td></mdl<></td></mdl<>	0.007	<mdl< td=""><td>mg/l</td></mdl<>	mg/l
lead	0.005	< MDL	<mdl< td=""><td><mdl< td=""><td><mdl< td=""><td>mg/l</td></mdl<></td></mdl<></td></mdl<>	<mdl< td=""><td><mdl< td=""><td>mg/l</td></mdl<></td></mdl<>	<mdl< td=""><td>mg/l</td></mdl<>	mg/l
selenium	0.004	<mdl< td=""><td><mdl< td=""><td><mdl< td=""><td><mdl< td=""><td>mg/l</td></mdl<></td></mdl<></td></mdl<></td></mdl<>	<mdl< td=""><td><mdl< td=""><td><mdl< td=""><td>mg/l</td></mdl<></td></mdl<></td></mdl<>	<mdl< td=""><td><mdl< td=""><td>mg/l</td></mdl<></td></mdl<>	<mdl< td=""><td>mg/l</td></mdl<>	mg/l
zinc	0.01	0.06	<mdl< td=""><td>0.01</td><td>0.01</td><td>mg/l</td></mdl<>	0.01	0.01	mg/l
mercury	0.0001	<mdl< td=""><td><mdl< td=""><td><mdl< td=""><td><mdl< td=""><td>mg/l</td></mdl<></td></mdl<></td></mdl<></td></mdl<>	<mdl< td=""><td><mdl< td=""><td><mdl< td=""><td>mg/l</td></mdl<></td></mdl<></td></mdl<>	<mdl< td=""><td><mdl< td=""><td>mg/l</td></mdl<></td></mdl<>	<mdl< td=""><td>mg/l</td></mdl<>	mg/l

SAMPLE ID AC02668 AC11017 AC026	69 AC11018

NOTES: 1. All samples were analyzed at the Kennecott Environmental Laboratory.

2. Both samples were collected from the entrance of the Pine Canyon tunnel.


Kennecott Utah Copper P.O. Box 525 Bingham Canyon, Utah 84006-0525 (801) 569-6506

Frederick D. Fox
Director, Environmental Affairs

Kennecott

January 30, 1995

Mr. Wayne Hedberg
Permit Supervisor
Minerals Reclamation Program
Division of Oil, Gas, and Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203



Subject: Annual Reports for 1994, Kennecott Utah Copper

Dear Mr. Hedberg:

Enclosed please find the annual report forms completed for the following mine permits:

• M/035/002 Bingham Pit & UCD Modernization and M/035/011 4th Line/Copperton Concentrator (active)

• M/045/004 Pine Canyon (active)

 M/035/005 Saltair North Impoundment (Note: name change for mine)

• M/035/015 North Perimeter
(Note: inactive, application has been superseded by application M/035/005 above)

If you have any questions on these annual reports, please call me.

Very truly yours,

Prederick D. Fox

FDF:bt

Enclosure